


All Dimensions In Inches[mm]
 Tolerance Inches:x.xx= ±0.02, x.xxx= ±0.010
 Millimeters:x.x= ±0.5, x.xx=±0.25



PIN CONNECTIONS			
PIN	FUNCTION	PIN	FUNCTION
1,2	+V Input	11	+Sense
3,4	-V Input	12	Trim
5	ON/OFF	13	-Sense
6	CASE	JP1	Short +S& +Vo
7,8	+V Output	JP2	Short -S& -Vo
9,10	-V Output		

Tabelle 1: Pinbelegung